

TO BE FILLED BY THE INSPECTING OFFICER PROVISIONAL FITNESS CERTIFICATE

1 Name of School(Old Age Home) : MAMBARAM ENGLISH MEDIUM SCHOOL,MAMBARAM

2 Name of Officer : GIREESH A, ASST. ENGINEER

3 Location : LSGD VENGAD GRAMAPANCHAYATH

KAITHERIPOYIL (PO)

4 Period for which the certificate is issued : Up to 31/03/2026

5 Types of Building : DETAILS IN Separate List Attached

6 Nature Of defect if any :

(a) Foundation and basement :

(b) Superstructure

(c) Doors and windows

(d) Wood work wrought and put up

(e) Roof

(f) Flooring

(g) Miscellaneous

7 Any major defects notice which will render the : No

8 Whether maintenance work have been done : yes.

9 Whether the structure is sound for

Accommodating inmates of the oldage home : yes. The structure is safe for accommodating inmates of the Oldage home under normal weather condition.

Notes:

1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on \_\_\_\_\_ and found to be fit to conduct classes for the period for the reason stated above.

Place:

Signature:

Date:

Designation:



Second Floor

Front	-6.10x6.10x3.70	7 Rooms
LHS	-6.10X6.10X3.70	4 Rooms
	-6.10x9.20x3.70	1 Room
RHS	-6.10X6.10X3.70	1 Room
	-5.45x6.10x3.70	1 Room
Back	-6.10x6.10x3.70	4 Rooms

Third Floor

Front	-6.10x6.10x3.0	2 Rooms
	-3.05X6.10X3.0	1 ROOM
	-2.95X8.32X3.00	1 ROOM
LHS	-5.15X6.10X3.00	1 ROOM
	-3.77X6.10X3.00	1 ROOM
	-6.10X6.10X3.00	1 ROOM
RHS	-6.10X6.10X3.00	2 ROOMS
BACK	-6.10X6.00X3.05	2 ROOMS(G1 Sheet roofing)
	-4.20x6.00x3.05	1 ROOM
	-8.00X6.00X3.05	1 ROOM

BUILDING NO:XIII-432

GROUND FLOOR	-6.20X6.10X3.50	4 ROOMS
FIRST FLOOR	-6.20X6.10X3.60	4 ROOMS
SECOND FLOOR	6.20X6.10X3.62	4 ROOMS